

Battery & Charging unit for RS02

Spare battery for friction welder RS02 CORDLESS 18V / 4Ah (72Wh)
Charging unit 4A / 230V for friction welder RS02 CORDLESS



Description
RS02 Battery

Order No.
FBWRS02AK18V



Description
LG4A Charging unit

Order No.
FBWRS02LG4A2